Revised: 07/11



SHEP SEAL 1315 UV

HIGH SOLIDS. NON-YELLOWING CURING AND SEALING COMPOUND

DESCRIPTION

Shep Seal 1315 UV is a solvent based curing and sealing compound specially designed to cure new concrete, assuring proper cement hydration and strength gain, while providing a non-yellowing seal to protect and enhance the appearance of concrete. This product is suitable for use on interior and exterior concrete surfaces. Shep Seal 1315 UV has excellent bonding characteristics and forms a continuous, glossy membrane to make the surface resistant to dirt penetration and other staining. Shep Seal 1315 UV is particularly suited for curing and sealing exterior concrete where membrane yellowing is undesirable.

PRIMARY APPLICATIONS

- Driveways & exterior pavements
- Walls and columns
- Terrazzo floors
- Parking garages
- Exposed aggregate
- Dry shake floors
- Freight terminals
- Curing and sealing decorative concrete

FEATURES & BENEFITS

- Helps promote development of concrete strength and durability
- Dustproofs concrete with a tough durable film
- Helps minimize spalling of exterior concrete
- Will not yellow under ultraviolet exposure

SPECIFICATIONS

- ASTM C 309, Type 1, Class A & B
- ASTM C 1315, Type 1, Class A
- AASHTO Specification M 148, Type 1, Class A & B
- USDA compliant

PACKAGING

Shep Seal 1315 UV is packaged in 55 gal (208 L) drums, 5 gal (18.9 L) pails and 4/1 gal (3.8 L) units per case.

DIRECTIONS FOR USE

Surface Preparation: The concrete surface must be clean and free of standing water. Remove any curing compounds, sealers, or other material that may prevent adhesion of the Shep Seal 1315 UV.

Mixing: Shep Seal 1315 UV requires no preblending and should be used directly from the container.

Application: Apply at a uniform coverage by spray or roller application. Product must be sprayed with a high pressure pump-up sprayer equipped with a high solids nozzle, or with an airless industrial sprayer. If roller applied, use a short napped, solvent resistant sleeve. Keep a wet edge

while spraying and backroll over sprayer lap marks for best appearance.

Curing and Sealing: For the best cure of freshly placed concrete, apply Shep Seal 1315 UV as soon as possible after finishing operations and/or immediately after the disappearance of the "sheen" of surface moisture. When sealing old concrete, the surface must be thoroughly clean and dry. Pressure washing with a strong alkaline detergent to remove dirt, waxes, and oil is suggested. Acids will not sufficiently clean or remove dirt, curing compounds, or old sealer from concrete. Worn or porous areas may need a second application for uniform seal and appearance.

TECHNICAL DATA

Typical Engineering Data

The following results were developed under laboratory conditions.

Drying time* @ 73°F, 50% RH <1 Recoat 2 to 24 Foot traffic 2 to 4 Wheel traffic 6 to 10	hours hours hours
Salt spray 500 hours exposure	
VOC content< 70 Adhesion to concreteexc	
Adhesion of asphalt tile	
	tance
48 hour exposureexc	ellent
Solvent resistancemi	nimal
Resistance to yellowingexc	ellent
Solids content>	
Moisture loss (ASTM C 156)< 0.40	kg/m ²
* Low concrete or air temperature and/or high relativ	e
humidity will extend drying time.	

Appearance: Shep Seal 1315 UV is a water clear liquid. After application and drying, Shep Seal 1315 UV offers a clear, glossy film. Shep Seal 1315 UV will darken concrete, masonry, pavers, etc., giving these materials a "wet" look. Follow recommended coverage rates carefully for best appearance.

For questions about this product, use our QR code



Continued on reverse side

COVERAGE

Coverage will vary from the above rates depending on surface porosity and texture. AVOID EXCESSIVE BUILDUP. HEAVY APPLICATIONS WILL LEAD TO DISCOLORATION AND POOR PRODUCT PERFORMANCE.

Application: ft²/gal (m²/L)	First Coat	Optional 2nd Coat
Curing and sealing new concrete	300-400 (7.4 - 9.8)	400-450 (9.8-11.0)
Sealing Older Concrete	400-450 (9.8-11.0)	450-550 (11.0-13.5)

Coverage will vary from the above rates depending on surface porosity and texture. AVOID EXCESSIVE BUILDUP. HEAVY APPLICATIONS WILL LEAD TO DISCOLORATION AND POOR PRODUCT PERFORMANCE.

CLEAN-UP

Tools and equipment may be cleaned with xylene, xylol or toluene. Run cleaning solvent through spray equipment to remove residual materials and prevent clogging of nozzle in future use.

REMOVAL

Dried, cured sealer may be removed with strong solvents such as xylene or acetone. Also acceptable are commercial paint strippers (always heed directions and warning labels). Alternatively, Shep Seal 1315 UV can be removed by sandblasting or by other similar mechanical action.

PRECAUTIONS

Material will not freeze in storage but should be allowed to rise to $50^{\circ}F$ ($10^{\circ}C$) before use.

- Do not apply when concrete surfaces or ambient temperatures are below 40°F (4°C). Application in hot direct sunlight, or when the concrete and/or air temperature is 90°F (32°C) and rising, may cause bubbling.
- Do not apply over bleed water or free standing water.
- Use with adequate ventilation and keep away from open flames. Block all HVAC ventilation ducts which may distribute solvent odor. If solvent odor is objectionable, use of a water based, low odor product may be preferred.
- For a high gloss finish, two thin coats of Shep Seal 1315
 UV is suggested rather than one heavy application. Apply the second coat within 24 hours of the first.
- Do not apply over concrete to receive toppings, epoxy or urethane-based coatings or adhesives. Although compatible with many carpet, tile and floor covering adhesives, a test section is recommended to ensure good bond

between the adhesive and Shep Seal 1315 UV.

- Do not use as a bond breaker for tilt-up construction.
- Do not use in areas subjected to hot grease or oils.
- Not resistant to gasoline or brake fluid.
- Do not thin this product.
- In all cases, consult the Material Safety Data Sheet before use.